

Pedestal Spot and Projection welders

All PW spot welders are built to last. Large transformers allow proper production duty cycles and rigid frames minimise deflection. Rocker arm units for light duty work and machines with direct acting cylinders for faster response and higher weld quality.

All welders up to 30kVA can be supplied with a range of controls, from the simple analogue WK to the sophisticated WS 2003 and WS4000 range, delivering all the high end control features required in high quality production environments.




Foot pedal Welders

SM15	15kVA Pedestal Welder, foot operated, with 400mm reach and Micro 8 control
SM20	20kVA Pedestal Welder, foot operated, with 400mm reach arms and Micro 8 Weld Control
SM30	30kVA Pedestal Welder, foot operated, with 400mm reach arms and Micro 8 Weld Control



Air operated Rocker Arm Welders

SP15	15kVA Pedestal Welder, foot operated, with 400mm reach and Micro 8 control
SP20	20kVA Pedestal Welder, foot operated, with 400mm reach arms and Micro 8 Weld Control
PED30	30kVA Pedestal Welder, air operated, with 450mm reach arms and WK Weld Control



Air operated Linear Welders

PED50	60kVA Pedestal Welder, air operated, with 450mm reach and WK Weld Control
PED100	100kVA Pedestal Welder, air operated, with 700mm reach and WS2003 weld control.
PED150	150kVA Pedestal Welder, air operated 700mm reach and WS2003 weld control. Features sliding beam head and very rigid construction for high duty work.



PW Sales

Tel: 01869-253688

Email: sales@portablewelders.ltd.uk

web: www.portablewelders.com